



ITEM · ARTICLE · ARTÍCULO · ARTIKEL · ARTIKEL · PRODOTTO · ARTYKUL

# 68123


↔ 203 x 75 x 9cm - 6'7" x 30" x 3.5"

🕒 WANDERLITE™ 2-IN-1 SLEEPING BAG & AIR PAD

🛒 1.76kg - 3.89lbs




**190T POLYESTER**  
Shell fabric  
Tissu extérieur  
Tejido de concha  
Außenmaterial  
Buitenstof  
Tessuto esterno  
Tkanina wierzchnia



**HOLLOW FIBER INSULATION**  
Thermal foam  
Mousse thermique  
Espuma térmica  
Thermo-Schaumstoff  
Thermisch schaum  
Schiuma termica  
Pianka termiczna



**190T POLYESTER**  
Lining  
Revêtement  
Recubrimiento  
Beschichtung  
Voering  
Fodera  
Podkład



**170G/M² HOLLOW FIBER**  
Padding  
Rembourrage  
Acolchado  
Füllung  
Vulling  
Imbottitura  
Wyściółka



**PUNCTURE-RESISTANT TOUGHLITE™ TPU**  
ToughLite™ résistant aux perforations  
ToughLite™ resistente a la perforación  
Reißfestem ToughLite™  
Schaderesistent ToughLite™  
ToughLite™ resistente alle forature  
Odporny na przebicie ToughLite™



**POCKET**  
Poche  
Bolsillo  
Tasche  
Zak  
Tasca  
Kieszka



**2-WAY ZIPPER**  
Fermeture éclair à 2 voies  
Cremallera de 2 vías  
2-Wege-Reißverschluss  
2-weg ritssluiting  
Cerniera a 2 vie  
Dwukierunkowy zamek błyskawiczny



**COMPACT PACKED SIZE**  
Taille de paquetage compacte  
Tamaño compacto  
Kompaktes Packmaß  
Handig verpakte grootte  
Dimensioni compatte  
Kompaktowy rozmiar



**MATTRESS HOLD SYSTEM**  
Le fourreau arrière s'adapte au matelas gonflable  
La funda trasera se adapta a la almohadilla de aire  
Back sleeve fits air pad  
Rückentasche dient zur Aufnahme sowie der Isomatte  
Il tessuto posteriore ne impedisce lo scivolamento durante l'uso  
Achterste mouw past op luchtpad


INCLUDES · Inclus · Incluye · Inhalt · Bevat · Include · Zawiera

**CARRY BAG**

Sac de transport - Bolsa de transporte  
Transport-tasche - Reistas  
Borsa da trasporto - Torba transportowa

**REPAIR KIT**

Kit de réparation - Kit de reparación - Reparaturkit  
Reparatiekit - Kit di riparazione - Zestaw naprawczy



#68123